



There is a shelled area where the pavement appears to be buckling

Aggressive high/low area where vehicle undercarriage consistently scrape/bottom out.







